## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,876,214 B2

Page 1 of 1

**APPLICATION NO. : 10/634598** 

INVENTOR(S)

: April 5, 2005 : Crook et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 9, line 49, in Claim 2, after "second probe" insert -- plate including a second --.

In column 9, line 50, in Claim 2, after "probe plate" insert -- , the second hole extending through the second probe plate --.

In column 10, line 7, in Claim 4, delete "tile" and insert -- the --, therefor.

In column 10, line 9, in Claim 5, delete "A" and insert -- An --, therefor.

Signed and Sealed this

Twenty-eighth Day of November, 2006

JON W. DUDAS Director of the United States Patent and Trademark Office